

IN THE UNITED STATES PATENT AND TRADEMARK OFFICE

Inventors: Burwell et al. Attorney Docket No. CHEN0189
 Patent No: 7,252,677 Group Art Unit: 3739
 Issued: August 7, 2007 Examiner: 6340
 Title: LIGHT GENERATING DEVICE TO INTRAVASCULAR USE

NOTIFICATION OF ERRORS

Bellevue, Washington 98004

August 22, 2007

TO THE COMMISSIONER FOR PATENTS:

The following errors were found during a review of the above-referenced United States Letters Patent. These errors were either inadvertently made in the original application or occurred in the printing of the patent. Since the errors are of an obvious nature, a formal Certificate of Correction is not believed to be warranted at this time. Therefore, it is requested that this notification be placed in the U.S. Patent and Trademark Office file.

| <u>Location in Patent</u> | <u>Error</u> |
|---------------------------|--|
| Column 2, line 44 | after "configured" insert --to-- |
| Column 6, line 58 | after "is" insert --a-- |
| Column 8, line 50 | after "polymers" insert --that-- |
| Column 8, line 55 | after "based" insert --upon-- |
| Column 8, line 62 | after "being" delete "is" |
| Column 9, line 53 | delete "to" insert therefor --too-- |
| Column 10, line 48 | delete "the" (1 st occurrence) insert therefor --be-- |
| Column 12, lines 19-20 | delete "relatively" insert therefor --relative-- |
| Column 14, line 54 | delete "devise" insert therefore --device-- |
| Column 15, line 44 | delete "lines" (1 st occurrence) |

1
2
3
4
5
6
7
8
9
10
11
12
13
14
15
16
17
18
19
20
21
22
23
24
25
26
27
28
29
30
31

Location in Patent

Error

Column 16, line 34

delete “describe” insert therefore --described--

Respectfully submitted,

/mike king/
Michael C. King
Registration No. 44,832